

**Make / Model**

Lexus Is IS 300 AUTO AWD CUIR ...

**Year**
**Mileage indicated / actual\***

2019

**98,761 km**
**Transmission**
**Drive Type**

automatic

AWD

**Engine**
**Fuel Type**

6 cyl. / 2 liters

unleaded

**Serial number**
**Stock number**

612634


**EQUIPMENTS**

Air conditioning, Cruise control, Heated Driver Seat, Adjustable steering wheel, ABS Brakes, Traction control, Rain sensor wipers, Sunroof, AM/FM stereo, Bluetooth, MP3 Player, Reverse camera, Onboard computer, Keyless start

**SALE PRICE**

# \$26,998

Plus tax.

**Owner and prior usage**

The following business or public organization leased or owned this vehicle long term :

This vehicle was previously used for :

The dealer will supply upon request the name and phone number of the last owner.

**Category**

Subject to admissibility of the transfer and the conditions and exceptions stated in the warranty contract, this vehicle comprises of a:

As per articles 159 and 160 of the consumer protection act, (1978,c9) this automobile is part of the category below and has a valid warranty for the duration of the term or mileage, whichever is attained first, indicated below:

 A  6 months or 10 000 km    B  3 months or 5 000 km    C  1 month or 1 700 km

 D  Good working (subject to 37, 38 L.P.C.)    E  No warranty

**Repairs done and mechanical verification certificate**

The following repairs have been done on this vehicle since the dealer's possession.

If necessary, the dealer will submit a mechanical verification certificate in accordance with the Highway Safety Code.

**Comments**
**Optional repairs**

The following defects have been noted on this vehicle and can be repaired at the cost mentioned below :

This evaluation is valid until delivery of the vehicle. I attest to having received a copy of the window sticker.

Date : \_\_\_\_\_ Signature : \_\_\_\_\_

autoExpert.ca

Sticker # : 8440252